ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
5

Ward Name
Jakkuru

Street ID
W0147, W0145, W0102, W0137, W0139, W0143, W0096, W

Street Name
NA, 3rd Crs, 13th Crs

Significant Landmark
Ambedkar nagara and Kattigenahalli colony

Segment No.
5/C-W0147/S011919

Total Length (m)
682.80

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	183.68	77.627599	13.123636	77.627465	13.121982	Palanahalli road	main road
2	180.56	77.627706	13.121996	77.627773	13.123627	Palanahalli cross road	dead end
3	56.64	77.625468	13.117862	77.625465	13.117350	Palanahalli cross road	dead end
4	45.09	77.625283	13.117361	77.625291	13.117768	Kattigenahalli colony	cross road
5	66.99	77.614480	13.115779	77.614531	13.116383	Kattigenahalli colony	cross road
6	104.70	77.613911	13.115800	77.614874	13.115730	Ambedkarnagara	2nd cross
7	45.14	77.614683	13.115320	77.614705	13.115727	Ambedkarnagara	1st cross

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements roads, Drains and removing resetting and covering slabs at Ambedakarnagara and Kattigenahalli colony in ward no. 05 Byatarayanapura sub d

Sanctioned Estimated Amount (Rs.)
10000000

Sanctioned Year
2018-19

Year
2018 - 2019

Type of Work
Others

Other Work Type
CC road and B.S Slab drains

Tender
Not a Tender

Work Details
CC road and B.S Slab drains

Job No. / Work Code
005-19-000003

Work Order No.
BBMP/EE/BTP/WO/143/2018-19

Work Order Date
17/10/2018

Period of Extention

Defect Liability Period From
23/11/2018

Defect Liability Period To
23/11/2019

Multiple road involved with the same Job No/ Work Code #
No

Field Inspection Details

Number of Trees	Any Other Information	Name
0		mahantesh kumar

Date of Inspection	Remarks
27/11/2018	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0147, W0145, W0102, W0137,

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M/s. KRIDL		0.00
Phone No.	**E-Mail ID**	
9900333496		

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0147, W0145, W0102, W0137,